S

Ø


O/

3 0

0

KOPPERS

August 19, 1986



Vicky Sanchez Industrial Waste Section Dept. of Public Works City of Houston P.O. Box 1562 Houston, Texas 77251

Re: Interim Industrial Waste Permit No. 26781 Koppers South Cavalcade Site

Dear Ms. Sanchez:

In accordance with the above referenced permit, please find enclosed analytical results for the third tank of wash water at the South Cavalcade site (Sample No. SCK-WW-01-07). The enclosed data are results from acid, base/neutral organics, BOD5, and TSS analyses. The data show that the water quality is not significantly different from before (total detected acid, base/neutrals of 85 ug/l), and therefore should be acceptable for discharge.

Per your request also please find enclosed a copy of the May 20, 1986 letter from Robert E. Hannesschlager of EPA to Greg Tipple of TWC.

Should you have any questions, please do not hesitate to contact me at

Sincerely yours,

Omr R. Compbell ames R. Campbell, Ph. D.

Project Manager,

Previously Operated Properties

Enclosure JRC:m

cc: J. Cochran (EPA)

bc: S. Craig

T. Hays

W. Tobin

File